



## RELEASE NOTE FOR ROUTER F5D6230-3, FIRMWARE 1.20.004

DATE: SEPTEMBER 11, 2002

---

These release notes describe features and caveats. The main code module for this release is compatible and downloadable into the switch over the network using the TFTP protocol. Please refer to the Installation and User Guide for a detailed description of the download procedure.

Refer to the Belkin User Guide for information about using the embedded web management capability of the switch.

This version of software **F5D6230-3-v1.20.004-runtime.bin** supports the following models of the F5D5130-x product family:

?? **F5D6230-3**

### **RESOLVED ISSUES**

1. **Virtual server of Netmeeting does not work.**
2. **Increase setup convenience to setup other settings without necessarily indicating wan mode parameters.**

### **PRE-RESOLVED ISSUES**

#### **V1.20.003**

1. **Disable then enable Dhcp server, renew ip of pc client gets wrong gateway address.**
2. **After restore factory defaults, as long as dhcp client gets ip, system crashes**

#### **V1.20.002**

1. **Disable Dhcp server will make system hang up.**
2. **EZ-Install API : Commit status wrong.**  
The commit status packets do not indicate errors correctly. Instead of the status code appearing at offset 6 it appears at offset 7 of the packet. Offset 6 is always zero.
3. **EZ-Install API : The WAN MAC address should always be set regardless of the addressing or authentication mode.**
4. **EZ-Install API : No port close after 10 min.**

#### **V1.20.001**

1. **Setup "LAN Service" page failed when using Netscape 4.5 , 4.7.**
2. **Fix SONY PS2 application compatibility problem.**
3. **Add EZ-Install API.**
4. **Add Release/Renew buttons in "Status" page.**
5. **Add non-standard FTP port configuration in "Virtual Server" page.**
6. **Add "Save Settings" button in "Tools" page to allow user to download gateway settings to a text file.**

#### V1.20.000

1. **Modify WAN driver access timer to fit new CPU (S3C4510B01).**
2. **Upgrade firmware fails when using IE on MAC OS X.**  
Change extension of firmware filename to .bin and add check in firmware to solve this problem.
3. **Support AppleTalk bridge between LAN and wireless.**
4. **Incorrect entry in web server log file.**

#### V1.10.005

1. **F5D5230-4 / F5D6230-3 User must login two times.**
2. **F5D5230-4 / F5D6230-3 Router cannot work with simple mail server names such as "Mail".**
3. **F5D5230-4 / F5D6230-3 Router has no entry for WAN Domain Name.**  
Add entry for WAN Domain Name in "LAN Services" page
4. **F5D6230-3 Router cannot bridge AppleTalk packets form wireless LAN to wire LAN.**
5. **Port 113 is detected "stealth" by port scanner .**  
Port 113 is open for News or linux-based applications. Now we dynamically open 113 port only for the News server but others, like server of port scanner. So the port scanner will show 113 port to be "stealth" and the News is still working.
6. **Can not connect to some web sites ([www.dellnet.msn.com](http://www.dellnet.msn.com), [www.citibank.com](http://www.citibank.com), [www.iwon.com](http://www.iwon.com)) when using PPPoE**  
Lower the MSS value of TCP connection initialization should be able to solve this probelm

#### V1.10.003

1. **Router keeps timing out and losing Internet connection.**  
Synchronized with latest version of code base because the problem did not appear in previous released debug firmware based the latest version of code base.
2. **Remove technical support hours in help page**