



RELEASE NOTE FOR ROUTER F5D7230-4, FIRMWARE 1.01.00

DATE: MARCH 12, 2003

These release notes describe features and caveats. The main code module for this release is compatible and downloadable into the switch over the network using the TFTP protocol. Please refer to the Installation and User Guide for a detailed description of the download procedure.

Refer to the Belkin User Guide for information about using the embedded web management capability of the switch.

This version of software **F5D7230-4_1.01.00** supports the following models of the F5D7230-x product family:

- **F5D7230-4**

RESOLVED ISSUES

1. **Extends compatibility with legacy 802.11b devices**
2. **Inability to Connect to the Internet:**
This update extends compatibility with Cable / DSL Internet Service Providers: Customers with ISPs that provide dynamic IP connections may have problems connecting the F5D7230-4 to their ISP.
3. **Virtual Server on port 80 does not work.**
4. **When DHCP Server is disabled, client will fail to access web pages.**
5. **Daylight savings time will adjust the time based on different time zones.**