



RELEASE NOTE FOR ROUTER F5D5230z4, FIRMWARE 1.20.002

DATE: SEPTEMBER 15, 2002

These release notes describe features and caveats. The main code module for this release is compatible and downloadable into the switch over the network using the TFTP protocol. Please refer to the Installation and User Guide for a detailed description of the download procedure.

Refer to the Belkin User Guide for information about using the embedded web management capability of the switch.

This version of software **F5D5230z4-v1.20.003-runtime.bin** supports the following models of the F5D5230-x product family:

- **F5D5230z4**

RESOLVED ISSUES

1. PPPoE idle time page can't display when pressed advance button in PPPoE setting page

PRE-RESOLVED ISSUES

V 1.20.002

2. Virtual server of Netmeeting does not work.
3. Increase setup convenience to setup other settings without necessarily indicating wan mode parameters.

V 1.20.001

1. After restore factory defaults, as long as dhcp client gets ip, system crashes

V 1.20.000

4. EZ-Install API : Commit status wrong.
The commit status packets do not indicate errors correctly. Instead of the status code appearing at offset 6 it appears at offset 7 of the packet. Offset 6 is always zero.
5. EZ-Install API : The WAN MAC address should always be set regardless of the addressing or authentication mode.
6. EZ-Install API : No port close after 10 min.
7. Porting from F5D5230-4 V1.20.002.

PRE-RESOLVED ISSUES

LIMITATION & RESTRICTIONS:

APPROVED BY:

Submitted By: _____

_____ Date

Product Manager

Date

Technical Support

Date

There are 2 types of firmware release, formal and engineering beta test version.

Formal version:

X.Y0 X: number from 1, Y: 0 - 9

Example: V1.00, and V1.10

Engineering Beta and Test version:

X.YZE X: number from 0, Y: 0 - 9 Z: 0 - 9

Example: V0.01E, V1.02E, or V1.14E