


F5D5050 Windows XP Installation Instructions

Now that you have properly installed the USB 10/100 Ethernet Adapter and it is properly connected to the network, we are now ready to configure the software to allow your computers to work together efficiently.


1. Turn on the power to the PC. Windows will automatically detect that a new device has been installed and will display the following windows.
 - A. WindowsXP will automatically detect the Ethernet Adapter.



- B. WindowsXP will install the drivers for the Adapter.



- C. You will be notified when the Drivers are installed.



Note: To confirm that the Adapter is installed and working properly, you will need to check the Device Manager.

Right click on the My Computer Icon and Select Properties. Select the Hardware Tab and click the Device Manager button. You will see an entry under Network Adapters. Left click on the “+” to expand Network Adapters you should see a listing for the BELKIN USB to Fast Ethernet Adapter. Double click on it; it will bring up the Status of Adapter. Under Device Status it should say, “This device is working properly”.

